=> d his

(FILE 'USPATFULL' ENTERED AT 15:41:28 ON 12 APR 2002)
         DEL HIS
     277 S (CMP OR POLISH? OR CHEMIMECH? OR PLANARIZ? OR LAP? OR GRIND?
L1 1509 S (CMP OR POLISH? OR CHEMIMECH? OR PLANARIZ? OR LAP? OR GRIND?
L2 1765 S L1 OR L2
L3   SET HIGH OFF
     476 S L3 AND (SEMICONDUCT? OR WAFER# OR CHIP#)
L4   SET HIGH ON
     476 S L3 AND L4
L5   116 S L1 AND L5
L6   33 S L6 AND (CMP OR POLISH? OR CHEMIMECH? OR PLANARIZ? OR LAP? OR
L7   83 S L6 NOT L7
L8   161 S L1 NOT (L7 OR L8)
L9   6 S L9 AND (CMP OR POLISH? OR CHEMIMECH? OR PLANARIZ? OR LAP? OR
L10 155 S L9 NOT L10
L11   SET HIGH OFF
     365 S L2 AND (SEMICONDUCT? OR WAFER# OR CHIP#)
L12   SET HIGH ON
     365 S L2 AND L12
L13 360 S L13 NOT L1
L14   SET HIGH OFF
       2 S L14 AND MASS?(3A)SPEC?
L15   SET HIGH ON
       2 S L14 AND L15
L16

=>